

1 ROB BONTA
Attorney General of California
2 CARL W. SONNE
Senior Assistant Attorney General
3 GREGORY J. SALUTE
Supervising Deputy Attorney General
4 State Bar No. 164015
600 West Broadway, Suite 1800
5 San Diego, CA 92101
P.O. Box 85266
6 San Diego, CA 92186-5266
Telephone: (619) 738-9431
7 Facsimile: (619) 645-2061
Attorneys for Complainant
8

9 **BEFORE THE**
10 **DEPARTMENT OF CONSUMER AFFAIRS**
11 **FOR THE BUREAU OF AUTOMOTIVE REPAIR**
STATE OF CALIFORNIA

12 In the Matter of the Accusation Against:

Case No. **79/20-9348**

13 **ANGEL ALONSO, A.K.A. ANGEL**
14 **ALONSO PARRA d.b.a. ANAHEIM**
SMOG
15 **1202 E. Lincoln Avenue,**
Anaheim, CA 92805

ACCUSATION

16 **Automotive Repair Dealer Registration No.**
17 **ARD 288993; Smog Check, Test Only,**
Station License No. TC 288993;

18 **ANGEL ALONSO PARRA**
19 **611 W. Victor Avenue,**
Anaheim, CA. 92801

20 **-and-**

21 **511 N. Philadelphia St. Apt. 203,**
22 **Anaheim, CA 92805**

23 **Smog Check Inspector License No. EO**
638929

24 **Respondent.**
25
26
27
28

1 **PARTIES**

2 1. Patrick Dorais (Complainant) brings this Accusation solely in his official capacity as
3 the Chief of the Bureau of Automotive Repair, Department of Consumer Affairs.

4 2. On or about November 20, 2017, the Bureau of Automotive Repair issued
5 Automotive Repair Dealer Registration Number ARD 288993 to Angel Alonso, aka Angel
6 Alonso Parra, dba Anaheim Smog (Respondents). The Automotive Repair Dealer Registration
7 was in full force and effect at all times relevant to the charges brought herein and will expire on
8 November 30, 2021, unless renewed.

9 3. On or about January 9, 2018, the Bureau of Automotive Repair issued Smog Check,
10 Test Only, Station License Number TC 288993 to Angel Alonso, aka Angel Alonso Parra, dba
11 Anaheim Smog (Respondent). The Smog Check, Test Only, Station License was in full force and
12 effect at all times relevant to the charges brought herein and will expire on November 30, 2021,
13 unless renewed.

14 4. On or about September 16, 2020, the Bureau of Automotive Repair certified Angel
15 Alonso, dba Anaheim Smog as a STAR Station. The certification will remain active as long as
16 the Automotive Dealer Repair Registration, and/or Smog Check Station License is revoked,
17 canceled, or the licenses become delinquent or the certification invalidated.

18 5. On or about January 21, 2016, the Bureau of Automotive Repair issued Smog Check
19 Inspector License Number EO 638929 to Angel Alonso Parra (Respondents). The Smog Check
20 Inspector License was in full force and effect at all times relevant to the charges brought herein
21 and will expire on May 31, 2022, unless renewed.

22 **JURISDICTION**

23 6. This Accusation is brought before the Director of the Department of Consumer
24 Affairs (“Director”) for the Bureau, under the authority of the following laws.

25 7. Section 9884.7 of the Business and Professions Code¹ provides that the Director may
26 revoke an ARD registration.

27 _____
28 ¹ All statutory references herein shall be to the Business and Professions Code unless
specifically stated otherwise.

1 11. Section 44072.10 of the Health and Safety Code states, in pertinent part:

2 ...

3 (c) The department shall revoke the license of any smog check technician or
4 station license who fraudulently certifies vehicles or participates in the fraudulent
5 inspection of vehicles. A fraudulent inspection includes, but is not limited to, all of
6 the following:

7

8 (4) Intentional or willful violation of this chapter or any regulation, standard, or
9 procedure of the department implementing this chapter. . . .”

10 **REGULATORY PROVISIONS**

11 12. California Code of Regulations, title 16, section 3340.24, subdivision (c), states:

12 The bureau may suspend or revoke the license of or pursue other legal action
13 against a licensee, if the licensee falsely or fraudulently issues or obtains a certificate
14 of compliance or a certificate of noncompliance.

15 13. California Code of Regulations, title 16, section 3340.30, states:

16 A smog check technician shall comply with the following requirements at all
17 times while licensed.

18 (a) A licensed technician shall inspect, test and repair vehicles in accordance
19 with section 44012 of the Health and Safety Code, section 44035 of the Health and
20 Safety Code, and section 3340.42 of this article. . . .”

21 14. California Code of Regulations, title 16, section 3340.35, states, in pertinent part:

22

23 (c) A licensed station shall issue a certificate of compliance or noncompliance
24 to the owner or operator of any vehicle that has been inspected in accordance with the
25 procedures specified in section 3340.42 of this article and has all the required
26 emission control equipment and devices installed and functioning correctly. . . .

27 15. California Code of Regulations, title 16, section 3340.42, sets forth specific emissions
28 test methods and procedures which apply to all vehicles inspected in the State of California.

29 **COST RECOVERY**

30 16. Section 125.3 of the Code provides, in pertinent part, that the Board may request the
31 administrative law judge to direct a licentiate found to have committed a violation or violations of
32 the licensing act to pay a sum not to exceed the reasonable costs of the investigation and
33 enforcement of the case, with failure of the licentiate to comply subjecting the license to not being

1 renewed or reinstated. If a case settles, recovery of investigation and enforcement costs may be
2 included in a stipulated settlement.

3 **VID DATA REVIEW**

4 17. Beginning March 9, 2015, California's Smog Check Program was updated to require
5 the use of an On-Board Diagnostic Inspection System ("OIS"). OIS is the Smog Check
6 equipment required in all areas of the State when inspecting most model-year 2000 and newer
7 gasoline and hybrid vehicles and most 1998 and newer diesel vehicles. The system consists of a
8 certified Data Acquisition Device ("DAD"), computer, bar code scanner, and printer. The DAD
9 is an On Board Diagnostic ("OBD") scan tool that, when requested by the California OIS
10 software, retrieves OBD data from the vehicle. All OBD data that the vehicle indicates it
11 supports is requested by the California OIS software and will be retrieved. The DAD connects
12 between the OIS computer and the vehicle's DLC. The California OIS software requires a
13 continuous Internet connection when performing a Smog Check inspection and the OIS software
14 communicates with BAR's central database through the Internet connection. The bar code
15 scanner is used to input technician information, the vehicles identification number ("VIN"), and
16 DMV renewal information. The printer provides a Vehicle Inspection Report ("VIR") containing
17 inspection results for motorists and a Smog Check Certificate of Compliance number for passing
18 vehicles.

19 18. Data retrieved and recorded during an OIS smog check includes; the eVIN, which is
20 the digitally stored VIN programmed into the vehicle's Powertrain Control Module ("PCM"); the
21 communication protocol, which is the manufacturer/vehicle specific language the PCM uses to
22 relay information; and the number of Parameter Identifications ("PIDs"), which is the number of
23 specific data values each PCM uses related to emissions controls.

24 19. If the vehicle passes the visual, functional and tailpipe tests, it passes the overall
25 inspection and a Certificate of Compliance is issued and transmitted electronically to the Vehicle
26 Information Database ("VID"). These Certificates of Compliance are purchased in blocks of fifty
27 (50) through the EIS or OIS from the VID, using a pre-arranged electronic bank account debit
28 system or by check, via mail, from Bureau Headquarters in Sacramento. Each Certificate of

1 Compliance has a unique control number so that it can be tracked to determine which Smog
2 Check Station purchased the Certificate of Compliance and to which vehicle it was issued.

3 20. The VID contains registration data from Department of Motor Vehicles (“DMV”)
4 plus emission standards, vehicle smog check inspections, smog check stations and technicians,
5 and Certificates of Compliance. The VID receives the passing smog check results immediately
6 following the inspection. During the vehicle registration process, the DMV accesses the VID to
7 verify that the vehicle has been tested and certified. The Bureau can also access the VID to view
8 test data on smog check inspections performed at any Smog Check Station, or search for, retrieve,
9 and print a test record for a particular vehicle which has been tested. The EIS or OIS, depending
10 on the test type, also prints a Vehicle Inspection Report (“VIR”), which is a physical record of the
11 test results and shows the Certificate of Compliance number that was issued if the vehicle passed
12 the smog inspection.

13 21. The smog check technician must sign the VIR under penalty of perjury to indicate
14 that the inspection was done within Bureau guidelines. Smog Check Stations are required by law
15 to maintain a copy of the VIR along with a copy of the repair invoice for three years. The
16 consumer’s VIR serves as a receipt and proof that the VID was updated and a Certificate of
17 Compliance was issued. Licensed Smog Check Technicians are the only persons authorized by
18 the Bureau to perform official inspections. They are issued a personal access code and a license,
19 which are used to gain access to the EIS and OIS to perform smog check inspections.
20 Unauthorized use of another technician’s access code or license is prohibited.

21 22. On or about August 4, 2020, in response to an automatic BAR97 lockout as a result
22 of Respondent Anaheim Smog transmitting improper data during the performance of a Smog
23 Check Inspection, Bureau representatives visited Anaheim Smog. They met with the owner
24 Alonso and a smog technician who was formerly employed at the facility. Bureau representatives
25 reviewed the records of Anaheim Smog provided by Respondent and found the following
26 discrepancies:

27 ///

28 ///

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

23. Vehicle #1:

Anaheim Smog invoice with attached VIR for a 1982 GMC K1500 Jimmy with CA license #5LAS150, documents a charge for a Smog Check Certificate of Compliance, while the VIR indicates “Overall Test Results FAIL” and that a certificate was not issued; a fraudulent act.

24. Vehicle #2:

Anaheim Smog invoice with attached VIR for a 1988 Toyota Pickup with CA license #3R80310 documents a charge for a Smog Check Certificate of Compliance, while the VIR indicates “Overall Test Results FAIL” and that a certificate was not issued; a fraudulent act.

25. Vehicle #3:

Anaheim Smog invoice with attached VIR for a 1998 Chevrolet S10 Pickup with CA license #5W79856 documents a charge for a Smog Check Certificate of Compliance, while the VIR indicates “Overall Test Results FAIL” and a certificate was not issued; a fraudulent act.

26. Vehicle #4:

Anaheim Smog invoice with attached VIR for a 1993 Geo Metro with CA license #3HFG364 documents a charge for a Smog Check Certificate of Compliance, while the VIR indicates “Overall Test Results FAIL” and a certificate was not issued; a fraudulent act.

27. Vehicle #5:

Anaheim Smog invoice with attached VIR for a 1992 Honda Accord with CA license #7KVT097 documents a charge for a Smog Check Certificate of Compliance, while the VIR indicates “Overall Test Results FAIL” and a certificate was not issued; a fraudulent act.

28. Vehicle #6:

An additional Anaheim Smog invoice attached to the identical VIR for a 1992 Honda Accord with CA license #7KVT097, listing a different customer and signature, documents a charge for a Smog Check Certificate of Compliance, while the VIR indicates “Overall Test Results FAIL” and a certificate was not issued; a fraudulent act.

///
///
///

1 29. **Vehicle #7:**

2 Anaheim Smog invoice with attached VIR for a 1992 Jeep Wrangler with CA license
3 #7ZYG687 documents a charge for a Smog Check Certificate of Compliance, while the VIR
4 indicates “Overall Test Results FAIL” and a certificate was not issued; a fraudulent act.

5 30. **Vehicle #8:**

6 Anaheim Smog invoice with attached VIR for a 1998 Dodge Dakota with CA license
7 #5V43138 documents a charge for a Smog Check Certificate of Compliance, while the VIR
8 indicates “Overall Test Results FAIL” and a certificate was not issued; a fraudulent act.

9 31. **Vehicle #9:**

10 Anaheim Smog invoice with attached VIR for a 2006 Ford F150 with CA license
11 #LYZZETE documents a charge for a Smog Check Certificate of Compliance, while the VIR
12 indicates “Overall Test Result FAIL” and a certificate was not issued; a fraudulent act.

13 32. **Vehicle #10:**

14 Anaheim Smog invoice with attached VIR for a 2007 Mercedes-Benz CLK 350 with CA
15 license #6MVC509 documents a charge for a Smog Check Certificate of Compliance, while the
16 VIR indicates “Overall Test Result FAIL” and a certificate was not issued; a fraudulent act.

17 33. **Vehicle #11:**

18 Anaheim Smog invoice with attached VIR for a 2004 Ford Econoline E350 Super Duty
19 Van with CA license #GINEL3 documents a charge for a Smog Check Certificate of Compliance,
20 while the VIR indicates “Overall Test Result NOT READY” and a certificate was not issued; a
21 fraudulent act.

22 34. **Vehicle #12:**

23 Anaheim Smog invoice with attached VIR for a 1999 Ford F150 Super Cab Short with CA
24 license #5Z77437 documents a charge for a Smog Check Certificate of Compliance, while the
25 VIR indicates “Overall Test Results FAIL” and a certificate was not issued; a fraudulent act.

26 35. **Vehicle #13:**

27 Anaheim Smog invoice with attached VIR for a 2005 GMC Yukon XL CI500 with CA
28 license #5LXP136 documents a charge for a Smog Check Certificate of Compliance, while the

1 VIR indicates “Overall Test Result NOT READY” and a certificate was not issued; a fraudulent
2 act.

3 **36. Vehicle #14:**

4 Anaheim Smog invoice with attached VIR for a 1999 Toyota Tacoma 2WD with CA
5 license #7E11965 documents a charge for a Smog Check Certificate of Compliance, while the
6 VIR indicates “Overall Test Results Gross Polluter” and a certificate was not issued; a fraudulent
7 act.

8 **37. Vehicle #15:**

9 Anaheim Smog invoice with attached VIR for a 2008 Nissan Altima 2.5 with CA license
10 #7LWU432 documents a charge for a Smog Check Certificate of Compliance, while the VIR
11 indicates “Overall Test Result NOT READY” and a certificate was not issued; a fraudulent act.

12 **38. Vehicle #16:**

13 Anaheim Smog invoice with attached VIR for a 2005 Toyota Camry Solara SE CA license
14 #7WXD891 documents a charge for a Smog Check Certificate of Compliance, while the VIR
15 indicates “Overall Test Result NOT READY” and a certificate was not issued; a fraudulent act.

16 **39. Vehicle #17:**

17 Anaheim Smog invoice with attached VIR for a 2010 Chevrolet Equinox LT with CA
18 license #7EED219 documents a charge for a Smog Check Certificate of Compliance, while the
19 VIR indicates “Overall Test Result NOT READY” and a certificate was not issued; a fraudulent
20 act.

21 **40. Vehicle #18:**

22 Anaheim Smog invoice with attached VIR for a 2006 Infiniti M35 Base with CA license
23 #7UJY916 documents a charge for a Smog Check Certificate of Compliance, while the VIR
24 indicates “Overall Test Result TAMPERED” and a certificate was not issued; a fraudulent act.

25 **41. Vehicle #19:**

26 Anaheim Smog invoice with attached VIR for a 2000 Toyota Camry LE with CA license
27 #4NRR379 documents a charge for a Smog Check Certificate of Compliance, while the VIR
28 indicates “Overall Test Result FAIL” and a certificate was not issued; a fraudulent act.

1 42. **Vehicle #20:**

2 Anaheim Smog invoice with attached VIR for a 2001 Ford F250 Super Duty with CA
3 license #69732P1 documents a charge for a Smog Check Certificate of Compliance, while the
4 VIR indicates “Overall Test Result FAIL” and a certificate was not issued; a fraudulent act.

5 43. **Vehicle #21:**

6 Anaheim Smog invoice with attached VIR for a 1996 Honda Civic with CA license
7 #3PZV520 documents a charge for a Smog Check Certificate of Compliance, while the VIR
8 indicates “Overall Test Results Fail” and a certificate was not issued; a fraudulent act.

9 44. **Vehicle #22:**

10 Anaheim Smog invoice with attached VIR for a 2001 Toyota Sienna CE with CA license
11 #7EFN888 documents a charge for a Smog Check Certificate of Compliance, while the VIR
12 indicates “Overall Test Result TAMPERED” and a certificate was not issued; a fraudulent act.

13 45. **Vehicle #23:**

14 Anaheim Smog invoice with attached VIR for a 2003 Ford Focus SE Comfort with CA
15 license #5CJL682 documents a charge for a Smog Check Certificate of Compliance, while the
16 VIR indicates “Overall Test Result FAIL” and a certificate was not issued; a fraudulent act.

17 46. **Vehicle #24:**

18 Anaheim Smog invoice with attached VIR for a 2000 Ford F150 with CA license #6F50076
19 documents a charge for a Smog Check Certificate of Compliance, while the VIR indicates
20 “Overall Test Result FAIL” and a certificate was not issued; a fraudulent act.

21 47. **Vehicle #25:**

22 Anaheim Smog invoice with attached VIR for a 2002 Dodge Ram 1500 with CA license
23 #13164C1 documents a charge for a Smog Check Certificate of Compliance, while the VIR
24 indicates “Overall Test Result TAMPERED” and a certificate was not issued; a fraudulent act.

25 48. **Vehicle #26:**

26 Anaheim Smog invoice with attached VIR for a 1996 Mazda Miata with CA license
27 #7KVS701 documents a charge for a Smog Check Certificate of Compliance, while the VIR
28 indicates “Overall Test Results Fail” and a certificate was not issued; a fraudulent act.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

49. Vehicle #27:

Anaheim Smog invoice with attached VIR for a 1997 Honda Prelude with CA license #5WQM987 documents a charge for a Smog Check Certificate of Compliance, while the VIR indicates “Overall Test Results Tamper” and a certificate was not issued; a fraudulent act.

50. Vehicle #28:

Anaheim Smog invoice with attached VIR for a 1996 Toyota Corolla with CA license #7PRT939 documents a charge for a Smog Check Certificate of Compliance, while the VIR indicates “Overall Test Results Fail” and a certificate was not issued; a fraudulent act.

51. Vehicle #29:

Anaheim Smog invoice with attached VIR for a 2000 Toyota Camry LE with CA license #4YWE325 documents a charge for a Smog Check Certificate of Compliance, while the VIR indicates “Overall Test Result DATA CHECK FAIL” and a certificate was not issued; a fraudulent act.

52. Vehicle #30:

Anaheim Smog invoice with attached VIR for a 1997 Toyota Camry with CA license #3THV490 documents a charge for a Smog Check Certificate of Compliance, while the VIR indicates “Overall Test Results Fail” and a certificate was not issued; a fraudulent act.

53. Vehicle #31:

Anaheim Smog invoice with attached VIR for a 1997 Buick LeSabre with CA license #4DJD333 documents a charge for a Smog Check Certificate of Compliance, while the VIR indicates “Overall Test Results Fail” and a certificate was not issued; a fraudulent act.

54. Vehicle #32:

Anaheim Smog invoice with attached VIR for a 1999 Ford Ranger Super Cab with CA license #63905W1 documents a charge for a Smog Check Certificate of Compliance, while the VIR indicates “Overall Test Results Fail” and a certificate was not issued; a fraudulent act.

///
///
///

1 authorized statements which he knew or in the exercise of reasonable care should have known to
2 be untrue or misleading, as follows: Respondent documented and charged a fee for a Smog
3 Check Certificate that was not issued or received by the customer. The vehicles referenced in
4 paragraphs 23 through 58 above failed the Smog Check Inspection and were not eligible to
5 receive a Smog Check Certificate of Compliance.

6 **SECOND CAUSE FOR DISCIPLINE**

7 **(Fraud)**

8 61. Respondent's registration is subject to disciplinary action pursuant to section 9884.7,
9 subdivision (a)(4), in that on and between June 22, 2020, through July 22, 2020, Respondent
10 fraudulently documented and charged a fee for a Smog Check Certificate that was not issued or
11 received by the customer. The vehicles referenced in paragraphs 23 through 58 above failed the
12 Smog Check Inspection and were not eligible to receive a Smog Check Certificate of
13 Compliance.

14 **THIRD CAUSE FOR DISCIPLINE**

15 **(Failure to Comply with the Automotive Repair Act)**

16 62. Respondent's registration is subject to disciplinary action pursuant to section 9884.7,
17 subdivision (a)(6), in that on and between June 22, 2020, through July 22, 2020, Respondent
18 fraudulently documented and charged a fee for a Smog Check Certificate that was not issued or
19 received by the customer. The vehicles referenced in paragraphs 23 through 58 above failed the
20 Smog Check Inspection and were not eligible to receive a Smog Check Certificate of
21 Compliance. Respondent was repeatedly admonished by the Bureau to follow the laws and
22 regulations pertaining to Automotive Repair Dealers and continued to violate those laws despite
23 being admonished.

24 **FOURTH CAUSE FOR DISCIPLINE**

25 **(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection)**

26 63. Respondent's station license is subject to disciplinary action pursuant to Health and
27 Safety Code section 44072.2, subdivision (c), in that on and between June 22, 2020, through July
28

1 22, 2020, Respondent failed to comply with the following provisions of the California Code of
2 Regulations, Title 16, as follows:

3 (a) **Section 3373:** Respondent fraudulently documented and charged a fee for a Smog
4 Check Certificate that was not issued or received by the customer. The vehicles referenced in
5 paragraphs 23 through 58 above failed the Smog Check Inspection and were not eligible to
6 receive a Smog Check Certificate of Compliance.

7 **FIFTH CAUSE FOR DISCIPLINE**

8 **(Dishonesty, Fraud or Deceit)**

9 64. Respondent's station license is subject to disciplinary action pursuant to Health and
10 Safety Code section 44072.2, subdivision (d), in that on and between June 22, 2020, through July
11 22, 2020, Respondent fraudulently documented and charged a fee for a Smog Check Certificate
12 that was not issued or received by the customer. The vehicles referenced in paragraphs 23 through
13 58 above failed the Smog Check Inspection and were not eligible to receive a Smog Check
14 Certificate of Compliance.

15 **SIXTH CAUSE FOR DISCIPLINE**

16 **(Dishonesty, Fraud or Deceit)**

17 65. Respondent's smog check inspector license is subject to discipline pursuant to Health
18 and Safety Code section 44072.2, subdivision (d), in that on and between June 22, 2020, through
19 July 22, 2020, Respondent fraudulently documented and charged a fee for a Smog Check
20 Certificate that was not issued or received by the customer. The vehicles referenced in paragraphs
21 23 through 58 above failed the Smog Check Inspection and were not eligible to receive a Smog
22 Check Certificate of Compliance.

23 **SEVENTH CAUSE FOR DISCIPLINE**

24 **(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection)**

25 66. Respondent's smog check inspector license is subject to disciplinary action pursuant
26 to Health and Safety Code section 44072.2, subdivision (c), in that on and between June 22, 2020,
27 through July 22, 2020, Respondent failed to comply with the following provisions of the
28 California Code of Regulations, Title 16, as follows:

1 (a) **Section 3373:** Respondent fraudulently documented and charged a fee for a Smog
2 Check Certificate that was not issued or received by the customer. The vehicles referenced in
3 paragraphs 23 through 58 above failed the Smog Check Inspection and were not eligible to
4 receive a Smog Check Certificate of Compliance.

5 **DISCIPLINE CONSIDERATIONS**

6 67. To determine the degree of discipline, if any, to be imposed on Respondent,
7 Complainant alleges that on July 15, 2019, the Bureau issued Angel Alonso d.b.a. Anaheim Smog
8 Administrative Citation #C2019-1684, for his actions in violation of section 44012 of the Health
9 and Safety Code, in that Respondent unlawfully inspected and certified a Bureau vehicle
10 documented to fail a properly performed Smog Check Inspection.

11 **OTHER MATTERS**

12 68. Pursuant to Business & Professions Code section 9884.7, subdivision (c), the Director
13 may suspend, revoke, or place on probation the registration for all places of business operated in
14 this State by Respondent Angel Alonso upon a finding that Respondent Angel Alonso has, or is,
15 engaged in a course of repeated and willful violations of the laws and regulations pertaining to an
16 automotive repair dealer.

17 69. Pursuant to Health & Safety Code section 44072.8, if Smog Check, Test Only,
18 Station License Number TC 288993 issued to Respondent is revoked or suspended following a
19 hearing under this article, any additional license issued under Chapter 5, Part 5, Division 26 in the
20 name of said licensee may be likewise revoked or suspended by the Director.

21 70. Pursuant to Health & Safety Code section 44072.8, if Smog Check Inspector License
22 Number EO 638929 issued to Respondent is revoked or suspended following a hearing under this
23 article, any additional license issued under Chapter 5, Part 5, Division 26 in the name of said
24 licensee may be likewise revoked or suspended by the Director.

25 **PRAYER**

26 WHEREFORE, Complainant requests that a hearing be held on the matters herein alleged,
27 and that following the hearing, the Director of the Department of Consumer Affairs issue a
28 decision:

- 1 1. Revoking or suspending Automotive Repair Dealer Registration Number ARD
- 2 288993, issued to Respondent Angel Alonso, aka Angel Alonso Parra, dba Anaheim Smog;
- 3 2. Revoking or suspending any other Automotive Repair Dealer Registration issued to
- 4 Respondent Angel Alonso;
- 5 3. Revoking or suspending Smog Check, Test Only, Station License Number TC
- 6 288993, issued to Angel Alonso, aka Angel Alonso Parra, dba Anaheim Smog;
- 7 4. Revoking or suspending Smog Check Inspector License Number EO 638929, issued
- 8 to Angel Alonso Parra;
- 9 5. Revoking or suspending any additional license issued under Chapter 5 of Part 5 of
- 10 Division 26 of the Health and Safety Code in the name of Respondent Angel Alonso aka Angel
- 11 Alonso Parra;
- 12 6. Ordering Angel Alonso aka Angel Alonso Parra to pay the Bureau of Automotive
- 13 Repair the reasonable costs of the investigation and enforcement of this case, pursuant to
- 14 Business and Professions Code section 125.3; and,
- 15 7. Taking such other and further action as deemed necessary and proper.

17 DATED: As of Digital Signature Date

PATRICK DORAIS
Chief
Bureau of Automotive Repair
Department of Consumer Affairs
State of California
Complainant

22 SD2021800899
23 82852063.docx